Route 9 signing changes in Haddam

Direction	Mile Point	Old Exit No.	New Exit No.	Old Legend	New Legend	Supplemental
North	12.77	8	13	EXIT 8 Beaver Meadow Rd Haddam 1 MILE	EXIT 13 Haddam 1 MILE	
North	13.27	8	13	EXIT 8 Beaver Meadow Rd Haddam V2 MILE	EXIT 13 Haddam 1/2 MILE	
North	13.61	8	13	EXIT 8 Beaver Meadow Rd Haddam	Exit 13 Haddam 🛪	
North	14.85	9	15	EXIT 9 81 Higganum 1 MILE	EXIT 15 81 Killingworth Road 1 MILE	
North	15.15	9	15			EXIT 15 Higganum
North	15.37	9	15	EXIT 9 81 Higganum V2 MILE	EXIT 15 81 Killingworth Road 1/2 MILE	
North	15.67	9	15	EXIT 9 81 7 Higganum	EXIT 15 81 Killingworth Road	
South	20.70	10	19	154 OUTH Aircraft Rd Higganum 1 MILE	EXIT 19 [154] SOUTH Aircraft Rd 1 MILE	
South	20.53	10	19			EXIT 19 Higganum

South	20.19	10	19	EXIT 10	EXIT 19	
				154 SOUTH Aircraft Rd Higganum 1/2 MILE	I54 SOUTH Aircraft Rd ^{1/2} MILE	
South	19.77	10	19	EXIT 10 154 Aircraft Rd Higganum	EXIT 19 154 SOUTH Aircraft Rd	
South	16.91	9	15	EXIT 9 81 Killingworth Clinton 1 MILE	EXIT 15 81 Killingworth Road 1 MILE	
South	16.65	9	15			EXIT 15 Killingworth Clinton
South	16.46	9	15	EXIT 9 81 Killingworth Clinton 1/2 MILE	EXIT 15 81 Killingworth Road 1/2 MILE	
South	16.04	9	15	EXIT 9 81 Killingworth Clinton	EXIT 15 81 7 Killingworth Road	
South	15.08	8	13	EXIT 8 Beaver Meadow Rd Haddam 1 MILE	EXIT 13 Haddam 1 MILE	
South	14.58	8	13	Exit 8 Beaver Meadow Rd Haddam V2 NILE	EXIT 13 Haddam 1/2 MILE	
South	14.28	8	13	EXIT 8 Beaver Meadow Rd Haddam	Exit 13 Haddam 🖈	